



Product: SiS Integrated 10/100 Fast Ethernet

Date: 08/22/2002

Document Type: Release Note

Driver Ver.: 1.16

Integrated LAN Driver [V1.16]

1. WindowsMe driver, Winodws2000 driver and WindowsXP driver certified by WHQL as for logo driver.

2. Bug fixed, Modification & Driver Version

[Windows XP]

a. Submission ID is 614635.

b. Fix the issue that Chang-mode(10Mb to 100 Mb or 100Mb to 10Mb) for ICS1893 PHYs.

c. Fix the issue that System cannot resume from S1 or S3 if LAN cable is connected.

[Windows 2000]

a. Submission ID is 616353.

b. Fix the issue that Chang-mode(10Mb to 100 Mb or 100Mb to 10Mb) for ICS1893 PHYs.

c. Fix the issue that System cannot resume from S1 or S3 if LAN cable is connected.

[Windows Me]

a. Submission ID is 616358.

b. Fix the issue that Chang-mode(10Mb to 100 Mb or 100Mb to 10Mb) for ICS1893 PHYs.

c. Fix the issue that System cannot resume from S1 or S3 if LAN cable is connected.

[Packet Driver]

a. Fix problem: Fail to install driver on SiS963.

[Novell client]

a. Fix Problem: Fail to install driver on SiS963.

b. Modify sample NET.CFG file.

[Novell server]

a. Fix Problem:Fail to install driver on SiS963.

Driver Version:

Windows 2000 ----- 1.16.01.00

Windows 98 ----- 1.16.01.00

Windows Millennium ----- 1.16.01.00

Windows 95 OSR2 ----- 1.16.00.00

Windows 95 ----- 1.16.00.00

Windows NT 4.0 ----- 1.16.00.00

Windows XP ----- 1.16.00.00

Windows for Workgroup ----- 1.15

Netware server 4.1x ----- 1.14

Netware server 4.2 ----- 1.14



Netware server 5.x -----	1.14
Netware server 6.0 -----	1.14
Netware client32 -----	1.12
Netware client -----	1.14
Packet driver -----	1.15
NDIS 2 for DOS -----	1.14
MS LAN Manager -----	1.14
NDIS 2 for OS/2 -----	1.14
DOS Diagnostic program -----	1.61
Windows 9x/2000 setup utility--	1.15
BootROM Rpl -----	1.15
PXE -----	1.09
PXERPL -----	1.09